




REPUBLIC OF ALBANIA



ALBANIAN CIVIL AVIATION AUTHORITY

AIRWORTHINESS DIRECTIVE

ACAA-DFS-AD-No.048

Issue: 01, Revision 00

Date: 10.10.2025

Approved by:
Maksim Et'hemaj

Executive Director of Albanian Civil Aviation Authority





0.1 Record of Amendments

The table below describes the dates and reason for the different amendments of the current procedure. A vertical black line on the left-hand side of the page identify the changes with the previous version.

Issue No.	Revision No.	Date	Amended by	Reason
01	00	10.10.2025	SAW	Initial Issue

0.2 Revision table

Page #.	Issue No.	Revision No.	Date	Edited by



1. Name of the AD:

ATA 57 – Wings – Pylon Spigot Fitting – Inspections

2. Issued and Effective Dates:

- Issued: 26 August 2025
- Effective Date: 09 September 2025

Revision:

Supersedure:

3. Full List of Aircraft Affected:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A319-173N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-253NY, A321-271N, A321-271NX, A321-271NY, A321-272N, and A321-272NX, aeroplanes, all manufacturer serial numbers (MSN).

4. Definitions:

For the purpose of this AD, the following definitions apply:

Affected part: Slotted nut having Part Number (P/N) D57250182200.

Serviceable part: Slotted nut having P/N D57253137200; or repaired parts having P/N R5724483020000, R5724483020200, R5724483020400, R5724483020600 or R5724483020800; or any slotted nut, eligible for installation in accordance with Airbus approved instructions, that is not an affected part.

Group:

Group 1 aeroplanes are those on which an affected part is installed.

Group 2 aeroplanes are those on which no affected part is installed.

An aeroplane having Airbus Modification (mod) 155617J4120 embodied in production is a Group 2, provided that no affected part has been installed since aeroplane date of manufacture on that aeroplane.

The AOT: Airbus Alert Operators Transmission (AOT) A57N025-25.

Aeroplane date of manufacture: The date of transfer of title (ownership) which is referenced in Airbus documentation at the time of first delivery to an operator.

5. Reason:

Following in-service occurrences, it was identified that severe corrosion could occur on the affected parts.

This condition, if not detected and corrected, could lead to loss and/or migration of the spigot sleeve, which could degrade

pylon and wing structure integrity.

To address this potential unsafe condition, Airbus issued the AOT providing instructions for repetitive general visual inspections (GVI) of the affected parts and, depending on the findings, corrective action(s).

For the reason described above, this AD requires repetitive GVI of the affected parts, and, depending on findings, accomplishment of applicable corrective action(s).

6. Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Inspection(s):

- (1) For Group 1 aeroplanes: Within the compliance time as defined in Table 1 of this AD, and, thereafter, at intervals not exceeding 12 months, inspect each affected part (left-hand (LH) and right hand (RH) sides) in accordance with the instructions of the AOT (see Note 1 of this AD).

Table 1 – Initial Compliance Time

Compliance time, A, B or C, whichever occurs later	
A	6 months after the effective date of this AD
B	12 months after the last accomplishment of the Maintenance Planning Document (MPD) task ZL-415-01 or MPD task ZL-415-02, as applicable, for the pylon (LH or RH) having that affected part installed
C	24 months after first installation of that affected part on an aeroplane

Note 1: The inspection as required by paragraph (1) of this AD can be accomplished during different maintenance visits for the LH and the RH affected parts.

Corrective Action(s):

- (2) If, during any inspection as required by paragraph (1) of this AD, discrepancies are detected, as defined in the AOT, before next flight, contact Airbus for repair instructions and accomplish those instructions accordingly within the compliance time specified therein.

Terminating Action:

- (3) For Group 1 aeroplanes: Replacement of each affected part of an aeroplane with a serviceable part in accordance with the instructions of the AOT, constitutes terminating action for the repetitive GVI, as required by paragraph (1) of this AD for that aeroplane.
- (4) For Group 1 aeroplanes: Accomplishment of the corrective action(s), as required by paragraph (2) of this AD, does not constitute terminating action for the repetitive GVI as required by paragraph (1) of this AD for that affected part, unless specified otherwise in the approved instructions provided by Airbus.

Part Installation:



- (5) For Group 1 and Group 2 aeroplanes: From the effective date of this AD, do not replace a serviceable part by an affected part on any aeroplane.

Reporting:

- (6) Within 3 months after the accomplishment of each GVI, as required by paragraph (1) of this AD, or within 3 months after the effective date of this AD, whichever occurs later, report the inspection results (including no findings) to Airbus. The AOT provides instructions which constitutes an acceptable method to comply with this requirement.

7. Ref. Publications:

Airbus AOT A57N025-25 at original issue dated 12 June 2025.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

8. Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 21 July 2025 as PAD 25-107 for consultation until 18 August 2025. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – 1IASA; E-mail: account.airworth-eas@airbus.com.

For full compliance please refer to:

<https://ad.easa.europa.eu/ad/2025-0185>

