




REPUBLIC OF ALBANIA



AUTORITETI I AVIACIONIT CIVIL

ALBANIAN CIVIL AVIATION AUTHORITY

AIRWORTHINESS DIRECTIVE

ACAA-DFS-AD-No.014

Issue: 01, Revision 00

Date: 12.07.2024

Approved by:



Maksim Et'hemaj

Executive Director of Albanian Civil Aviation Authority

0.1 Record of Amendments

The table below describes the dates and reason for the different amendments of the current procedure. A vertical black line on the left-hand side of the page identify the changes with the previous version.

Issue No.	Revision No.	Date	Amended by	Reason
01	00	12.07.2024	SAW	Initial Issue

0.2 Revision table

Page #.	Issue No.	Revision No.	Date	Edited by

1. Name of the AD:

EASA AD No. 2024-0106, ATA 44 – Cabin Systems – Antenna Adapter Plate – Inspection

2. Full Description of the AD:

The AD addresses potential corrosion and cracking issues on specific parts of Airbus A319, A320, A321, A330, A350, and A380 aircraft related to antenna adapter plates.

3. Issued and Effective Dates:

Issued: 31 May 2024

Effective: 14 June 2024

4. Full List of Aircraft Affected:

Airbus A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133
Airbus A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N
Airbus A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N, A321-272NX
Airbus A330-201, A330-202, A330-203, A330-223, A330-243, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-841, A330-941
Airbus A350-941, A350-1041
Airbus A380-841, A380-842, A380-861.

5. Description of How It Can Be Resolved:

The AD requires repetitive inspections and, if necessary, corrective actions to address potential corrosion and cracking on affected parts. Compliance is required as per the instructions in the associated Airbus Service Bulletins and Panasonic SBs.

For full compliance please refer to :

https://ad.easa.europa.eu/blob/EASA_AD_2024_0106.pdf/AD_2024-0106_1