



REPUBLIKA E SHQIPËRISË
AUTORITETI I AVIACIONIT CIVIL
DREJTORI EKZEKUTIV

Nr. 87 prot.

Tiranë, më 28.07.2024

VENDIM

Nr. 88, datë 28.07.2024

PËR

**PRANIMIN DHE PUBLIKIMIN E DISA DIREKTIVAVE TË VLEFSHMËRISË
AJRORE PËR ZBATIMIN E URDHËRIT TË MINISTRIT NR. 79, DATË 15.04.2024**

Në mbështetje të neni 14, pika (ë), të Ligj Nr.53/2022 “Për organizimin dhe funksionimin e Autoritetit të Aviacionit Civil” dhe në zbatim të pikës M.A.303, Pjesa M, Seksioni A, Nënpjesa C, e Urdhërit të Ministrit Nr.79, datë 15.04.2024, për miratimin e rregullore “Mbi vazhdueshmërinë e vlefshmërisë ajrore të avionëve dhe produkteve, pjesëve dhe pajisjeve aeronautike dhe mbi miratimin e organizatave dhe personelit të përfshirë në këto detyra”,

V E N D O S A

1. Për zbatimin e Urdhërit të Ministrit Nr.79, datë 15.04.2024, për miratimin e rregullore “Mbi vazhdueshmërinë e vlefshmërisë ajrore të avionëve dhe produkteve, pjesëve dhe pajisjeve aeronautike dhe mbi miratimin e organizatave dhe personelit të përfshirë në këto detyra”, pranohen Direktivat e Vlefshmërisë Ajrore të nxjerra nga EASA, gjatë periudhës Janar- Maj 2024, bashkëlidhur këtij vendimi, të renditura si më poshtë:
 - EASA AD No.: 2024-0022, ATA 32 - Landing Gear - Nose Landing Gear - Repair Assessment me kod ACAA-DFS-AD-No.001;
 - EASA AD No.: 2024-0027, ATA 57 - Wings - Bottom Wing Skin Panel 2 - Inspection me kod ACAA-DFS-AD-No.002;
 - EASA AD No.: 2024-0030, ATA 05 - Time Limits/Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment me kod ACAA-DFS-AD-No.003;
 - EASA AD No.: 2024-0031, ATA 05 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations - Amendment me kod ACAA-DFS-AD-No.004;
 - EASA AD No.: 2024-0038, ATA 25 - Equipment/Furnishings – Galleys - Inspection me kod ACAA-DFS-AD-No.005;

- EASA AD No.: 2024-0046, ATA 05 - Time Limits/Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements Amendment me kod ACAA-DFS-AD-No.006;
- EASA AD No.: 2024-0047, ATA 05 - Time Limits/Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment me kod ACAA-DFS-AD-No.007;
- EASA AD No.: 2024-0068, ATA 53 - Fuselage – Lateral Cockpit Window Frame Upper Stiffener - Inspection me kod ACAA-DFS-AD-No.008;
- EASA AD No.: 2024-0077, ATA 53 - Fuselage – Pressure Panel Longitudinal Beams-Inspection/Repair/Modification me kod ACAA-DFS-AD-No.009;
- EASA AD No.: 2024-0066, ATA 05 - Time Limits/Maintenance Checks – Safe Life Airworthiness Limitations Items – ALS Part 1 – Amendment me kod ACAA-DFS-AD-No.010;
- EASA AD No.: 2024-0089, ATA 53 – Fuselage-Main Landing Gear Bay Rear Panel-Inspections me kod ACAA-DFS-AD-No.011;
- EASA AD No.: 2024-0097, ATA 53 – Fuselage-Centre Fuselage/Main Landing Gear Door Keel Beam Hinge and Actuator Fittings-Inspection me kod ACAA-DFS-AD-No.012;
- EASA AD No.: 2024-0097R1, ATA 53 – Fuselage-Centre Fuselage/Main Landing Gear Door Keel Beam Hinge and Actuator Fittings-Inspection me kod ACAA-DFS-AD-No.013;
- EASA AD No.: 2024-0106, ATA 44 – Cabin Systems – Antenna Adapter Plate-Inspection me kod ACAA-DFS-AD-No.014.

2. Ngarkohet Drejtoria e Standardeve të Fluturimit, në veçanti Sektori i Vlefshmërisë Ajrore, për ndjekjen e zbatimit të këtij vendimi.
3. Ngarkohet Drejtoria e Standardeve të Fluturimit të marrë masa për njoftimin apo publikimin për zbatim nga operatorët të Direktivave të mësipërme.
4. Ky vendim hyn në fuqi menjëherë dhe publikohet në faqen zyrtare të internetit të Autoritetit të Aviacionit Civil.

DREJTOR EKZEKUTIV

Maksim Et'hemaj

